

Model: PC8000

Serial #: See Affected Units

Aug. 12, 2019

Product Bulletin # PC-038 v 1.0

Indexer Reinforcement

Canrig has released a procedure to reinforce the indexers set collars on the Automated Power Catwalk. The set collar was originally welded only on the outside of the indexer and not on the inside which resulted in having the set collar breaking off the indexer over time.







Figure 1: Catwalk Indexers Set Collars

Affected Units

All Canrig[®] Automated Power Catwalk 8000 (PC8000) units.

Recommended Action

Contact RIGLINE 24/7™ Support to schedule a technician to perform this procedure.